




Simple to Operate and Clean

To adjust paint flow - For more paint, turn airbrush tip counter-clockwise. For less paint, turn paint nozzle tip clockwise. For finer detail get as close to the surface as possible and release a very small amount of paint. For broader coverage pull back from the surface and open the tip for more paint. For best spray results thin paint to a light cream consistency or thinner.

Clean is simple - Just unscrew paint jar and empty remaining paint then wipe out with rag or paper towel. Fill jar half full with thinner and spray for five seconds or more. Pour out remaining thinner and again wipe out jar till clean.

For more complete instruction go to our Web Site at www.paascheairbrush.com

Paasche Airbrush Co.

9511 58th Place

Kenosha, WI 53144

Phone: (800) 621-1907

Website: www.paascheairbrush.com

E-Mail: info@paascheairbrush.com

EZ-STARTER AIRBRUSH SET



Made in China for Paasche Airbrush